Chongqing, China

ROCKER ARM ERR3342 ERR3343 10559 for Land Rover Defender Discovery 300 Tdi Engine

If we have stock ,we can ship within 3 days , the exact delivery time depends on order $% \left({{{\rm{A}}_{\rm{B}}} \right)$

Basic Information

- Place of Origin:
- Minimum Order Quantity: Negotiable
- Price: \$3.00/pieces 50-199 pieces
- Packaging Details: Carton box/Pallet /wooden box

quantity L/C, T/T

- Delivery Time:
- Payment Terms:



gqing) Auto Parts Cg (ch

Product Specification

- Product Name:
- Condition:

• OE NO.:

Warranty:Application:

- ROCKER ARM New ERR3342 ERR3343 10559 1YEAR
- For Land Rover Defender Discovery 300 Tdi



More Images



Product Description



PRODUCT SPECIFICATIONS

Product name	ROCKER ARM
OEM#	ERR3342 ERR3343 10559
Application	FOR Land Rover Defender Discovery 300TDi
Packing method	As per customer's requirements
Place of Origin	China
Warranty	12 months





COMPANY PROFILE

Ximeng parts is a professional auto supplier with more than 19 years's experience , we specialized in engine parts for all kinds of cars , and also supply transmission parts, suspension parts and body parts.

We fous on high quality , provide excellet service , devote to be the reliable partner and supplier of our clients .

Our major market is South Amercia, North Amercia, Eastern Europe ,

Ocea-nia ,Middle East , Central Amercia, South Asia, Southeast Asia



PRODUCT LINES

Engine parts : Long block , cylinder head , camshaft crankshaft , oil pump ,

water pump , starter , alternator , conrod , rocker arm .

Suspension parts: shock absorber , control arm , engine mount ,bearing,etc.

Transmission parts: gear box , gear, shaft, etc.

Steering systems: Steering rack , steering pump , wheel hub , drive shaft

Body parts : hand door, lamp, mirror. Door lock,etc.

THE FACTORY WORKSHOP



PACKAGING TO SHOW









+8615736661500 iximengparts@foxmail.com
auto-enginepart.com
1109, Shiguangli Building 14, Daxuechengnan Road, Gaoxin district, Chongqing,China